

## **DUINDIGT** RACECOURSE

Vooroverlegplan May 2018

# CONCEPT PROPOSAL

Sustainable development plan



## TABLE OF CONTENTS

1	Concept	1
	Plans	2
	Program	5
	Overview buildings	6
2	Concept explanation	7
	Cultural history	8
	Urban form	13
	Green	16
	Traffic	18
	Parking	19

## 1 CONCEPT

## CONCEPT PLAN

#### SMALL TRIBUNE

TRIBUNE

.....



PUBLIC PARKING

Ρ





SHORTSTAY

10111.....

HOTEL



RACETRACK



Ρ

DWELLINGS

**OPEN AIR LANDSCAPE STABLES** 




## EXISTING SITUATION

-11

### PROGRAM

8.580 m2	<b>SHORT STAY</b> 22 buildings, 3-4 units each		28.6%	SHORT STAY
2.100 m2	PARKING SHORT STAY		11.7%	RESIDENCES
3.500 m2 900 m2	RESIDENCES 20 units PARKING RESIDENCES	GROSS FLOOR AREA BUILT PROGRAM 30.000 m2 (x 3.2m height = 96.000 m3)	29.0%	HOTEL
8.700 m2	HOTEL 100-120 rooms			
3.000 m2	PARKING HOTEL		30.7%	TRIBUNE
9.220 m2	spectator seating, offices		100-120 stables 70 spots	PARKING SHORT STAY
3000 m2	LANDSCAPE STABLES	<b>OPEN AIR</b> 910 Parking spots	30 spots 100 spots	PARKING RESIDENCES
21.300 m2	EXISTING VISITOR PARKING*		710 spots	EXISTING VISITOR PARKING*

### **OVERVIEW BUILDINGS**



## CONCEPT EXPLANATION

## BRING BACK THE INTANGIBLE EQUESTRIAN CULTURE TO DUINDIGT





## SUGGESTED HERITAGE BUILDINGS

KEEP THE BUILDINGS THAT ARE IMPORTANT TO THE CULTURAL EXPERIENCE OF DUINDIGT

Act strater to the stable of t

Buildings with high cultural-historic value

Buildings with lesser cultural-historic value, due to changes

## FURTHER INVESTIGATION REQUIRED

#### DOUBTS ON THE ACTUAL VALUE OF THE TRIBUNES & STABLES FOR POSSIBLE RE-USE OR TRANSFORMATION





- Broken doors & fences
- Bent steel bars


- Building itself in original condition
- Can be restored
- Worth keeping






- Deteriorating walls, electrical fixtures outside
- No rooflights
- Roof needs to be replaced

- New stable doorsRemoved chimney
- New, simpler loading hatch doors -Heritage quality is questionable













Repairs and fixes were done with a very poor qualityDegraded facades need replacement

- Highly degraded concrete
- Safety of tribune might be compromised
- Structural assessment needed by professionals


## **BRING BACK EQUESTRIAN CULTURE**

ADD COMPLEMENTARY PROGRAM WHICH SUPPORTS, PROMOTES & DIVERSIFIES EQUESTRIAN ACTIVITIES ON THE PLOT



## **GEBIEDSVISIE GUIDELINES INTEGRATED IN CONCEPT**









**URBAN FORM** 

## CONCEPTUAL ZONING TO MAINTAIN LANDSCAPE QUALITIES

ADD MORE TREES

HOTEL

PILS

DENTR

New buildings embedded in forest edge

DEVELOPMENTS

CORRIDOR CORRIDOR

NEW TRI

FOREST

BUNES

Plant new trees, fill empty areas forest

REUSE OLD STABLES

NEW SHORT STAY

Create green and open beach plains

RANSITION ZONE

Create continuous residential area along waalsdorperlaan

**URBAN FORM** 

## ADJUST NEW BUILDINGS TO THE EXISTING LANDSCAPE QUALITIES



## MAINTAIN SEQUENCE OF OPEN BEACH PLAINS AS GREEN CORRIDOR

erising treatine Narrowing of corridor

FOREST

CORRIDOR


Landscape stables covered with grass

Shift treeline towards back of plot to cover existing & new residences

Narrowing of corridor

GREEN

### ADDITIONAL MEASURES TO IMPROVE LANDSCAPE QUALITIES





New equestrian facilities New road structure New buildings

GREEN

BEFOR

